

Calibration chamber for hygrometers (Wet and dry air mixing type)



< Specifications >

Range : 15 to 95 [%RH]


Accuracy: ± 2 [%RH] (at 25 °C)

Dimensions (Internal): W750 x H700 x D700 mm

< Purpose of use >

This is used to compare and calibrate hygrometers.

< System >



[diagram of system]