

Calibration chamber for thermometers (Air chamber type)



< Specifications >

Range : -40 to +50 [°C]

Accuracy: ± 0.3 [°C]

Dimensions (Internal): W600 x H850 x D800 mm

< Purpose of use >

This is used to compare and calibrate thermometer equipment such as bimetal thermographs and radiosondes whose sensors and recorders are integrated and cannot be separated.