


30. The Off Hamamura, Tottori, Earthquake, 1943




(March 5th, 04:50. $35^{\circ}42'N$, $134^{\circ}06'E$, $r=475$ km, $M=6.8$)

Damage together with that due to the shock occurring the day before was 11 slight injured, 66 razed, 594 half destroyed houses, etc.

Seismographs

No Fig.	Station	Int.	Inst.	Comp.	V	T	r	v	ps	No m. f.
1	Tadotsu	IV	P	{ N E	50	3	0.005 0.004		25.2	6



1. Tadotsu (P)