
700 km,

ude, its sunami lamage, was ob-Teshio. s were afferred ts were lig tsu-Rishiri ships. Deserved and. It

in Har-




(July 15th, 23:45. 36°42′N, 138°16′E, r=201 km, M=6.6)


Though not of large magnitude, the shock was so strong locally that it caused casualties of 5 dead, 3 serious, 15 slight injured, 29 totally destroyed, 115 half destroyed houses, 48 totally destroyed, 122 half destroyed huts in Nagano City and its neighbourhood.

Seismographs

								· · · · · · · · · · · · · · · · · · ·		
No Fig.	Station	Int.	Inst.	Comp.	V	Т	r	v	ps	No m. f.
1	Nagano	IV	P(0)	Н	50	4.0	0.037		_	47
2	//		P	"	//	"	//		24.5	44
3	"		0	Н	20	17	0.004		24.9	18 46
4,5	,,		W	∫ E N	79 85	4.2 3.9	$0.02 \\ 0.02$	$\frac{2.6}{2.6}$	33.0	177
	7			( v	54	3.8	0.03	2.3	27.3	178




1. Nagano (P) Aftershock




4. Nagano (WH)



4. Nagano (WV)



2. Nagano (P)



3. Nagano (O)